




Repair Report of K24C00103-1 

Customer Information

Sold-To Account : 光华荣昌	Repair Fee :
Sold to Company ID :	RMA PO# :
Contact Person : 张强	Cust. Return PO# :
Contact Phone No. : 18812172925	Invoice No. :
Email Address : linwu.chen@advantech.com.cn	
Ship-To Account : 光华荣昌	Ship-To TEL :
Ship-To Company ID :	Ship-To FAX :
Ship-To Attention : 张强	Contact Phone No : 18812172925
Ship-To Address : 河北省沧州市黄骅市开发区光华荣昌 河北 0 ?? 1	Shipping Instruction :

Product Information

Product : PCI-1711U-CE 	Serial No : IAAA425909 
Cust. Reference# :	Revision :
Original RMA No :	Warranty : 05/05/2020
Cust. Product : IAAA425909	Battery : Attached : N
Receiving Remark :	
Pending Remark :	
SOP Revision :	
Test Fixture Revision :	

Repair Information

Problem Description : IO口输出异常
<input type="checkbox"/> Duplicated Before Fixing <input type="checkbox"/> Another Problem Found

Repaired By : FENG.KANG1 康治国 0512-57775666 8388 IQC Check : Clean Check complete,Gape Check complete,Label Check complete Repair Result : Repaired Test/Repair Update : <ol style="list-style-type: none"> 1.经过检测发现DI故障 2.外观检查正常 3.检测发现D27 TVS管、U29逻辑芯片损坏 4.更换D27;U29，测试功能恢复正常，全功能测试PASS，客户问题解决。 FQC Check : Navigator

当您在 RMA 服务上有任何问题时，请致电：0512-57775666# 8387/8383
 Should you have any queries about RMA service, please call 86-512-57775666# 8398/8389